



Gearbox Mounting Positions


Last updated 1 year ago




B3




B8




V5




V6




B6




B7




F1, Left (Output Flange)




F1, Right (Output Flange)




B Left (Torque Arm)




B Right (Torque Arm)




A1 Left (Output Shaft)



A1 Right (Output Shaft)



A2 (Output Shaft)



Position of motor terminal box